

[REDACTED]
The Report Date is 6/8/2015 9:36:00 AM.









SUMMARY HIGHLIGHTS	
Report Type:	Equipment
Job Number:	55505
Borrower or Lessee:	[REDACTED]
Loan or Lease Reference Number:	[REDACTED]
Requested Date:	5/28/2015 10:01:26 AM
Completion Date:	6/8/2015 8:54:51 AM
Facilitator:	Peggy Thew


Thank you for your business and the opportunity to assist you. Every effort has been made to ensure the information contained herein is accurate. Please review the contents of the report and contact us immediately if discrepancies are noted. Modifications will only be made to this report within 3 business days from the report date.

147 West Election Road | Suite 200 | Draper, UT 84020 | P 801 523 8449 | F 801 820 8223 | www.assetinspection.net www.leaseinspection.com


Inspected Address	
Address 1	402 Davidson Street
Address 2	
City	Nashville
State/Province	TN
ZIP/Postal Code	37213
EQUIPMENT	
To Whom Did You Speak ? *	Name : Patrick Thompson Title : General Manager
Does the Company plan to finance any other equipment during the next 12 months ?	No
Did You Personally View All The Equipment ?	Yes
VIN	
Serial Numbers	2012 Dubois Curtain Coating Line - In-feed Conveyor: 5008 - 2012 Dubois Curtain Coating Line - Middle Conveyor: 5008 - 2012 Dubois Curtain Coating Line - Belt Conveyor: 5009 - 2012 Dubois Curtain Coating Line - Oven Unit: 5010 - 2012 Dubois Curtain Coating Line - Main Disconnect: 5025 -
Did You Personally View The Equipment At The Specified Address ?	Yes
Number Of Items Inspected *	5
Is The Equipment New Or Used ?	New
List Missing Equipment	None
When Were You Told The Equipment Was Delivered ? *	4/24/2015 First piece of equipment arrived 4/24/2015; remaining equipment arrived 5/8/2015.
Is Any Of The Equipment Attached To Real Property, A Titled Vehicle or a Trailer (Bolted Down, etc.)?	Yes All equipment has been bolted to floor of building at the specified address.
When Were You Told The Equipment Was Installed ? *	6/5/2015 Installation of equipment began shortly after all components arrived and had been inspected. However, final installation has not yet been completed.
Describe The Condition Of The Equipment	Other than one roller being damaged on the in-feed conveyor, the equipment is in good condition.
Was Equipment In Operation When Viewed ?	No Final installation is still in-progress. It was verbally confirmed that some components have been powered on/partially operated, but not all of them are ready for production process.
Were There Any Discrepancies Between The Company Name, Address Or Phone Number ?	No There was no business signage posted.
BUILDING AND PREMISES	
Exterior Appearance : Front	Fair
Exterior Appearance : Back	Fair
Interior Appearance	Fair
Neighborhood	Industrial
Years in Business *	5
Number of Employees Company says are at this location.*	20
Number Of Employees Viewed At This Location. *	20
Number Of Employees At Any Other Location.	0

Is Company Satisfied With The Equipment ?	Yes	
I Certify To The Best Of My Knowledge That The Information Reported Herein Is Truthful & Accurate.		
Coordinated By:	Peggy Thew	
Inspected By	Dale Beardslee	Date : 6/8/2015 Time 08:54 AM
Reviewed By	Sarah Achtziger	Date : 6/8/2015 Time 10:35 AM


 <p>VIN/Serial#/Hull# 5008 Serial # plate: 2012 Dubois Curtain Coating Line - In-feed conveyor</p>	 <p>Subject None Side view of conveyor where boards are coated with fire retardant material</p>
 <p>VIN/Serial#/Hull# 5008 Serial # plate: 2012 Dubois Curtain Coating Line - Middle conveyor</p>	 <p>VIN/Serial#/Hull# 5009 Serial # plate: 2012 Dubois Curtain Coating Line - Belt conveyor</p>
 <p>VIN/Serial#/Hull# 5010 Serial # plate: 2012 Dubois Curtain Coating Line - Oven unit</p>	 <p>VIN/Serial#/Hull# 5025 Serial # plate: 2012 Dubois Curtain Coating Line - Main disconnect</p>
 <p>Subject None 2012 Dubois Curtain Coating Line - Main disconnect</p>	 <p>Subject None Side view of oven unit</p>




Rear View
End unit where finished product is stacked prior to packaging




Other
Finished product (produced using existing equipment, not new equipment)




Subject
Side view of oven




Subject
Side view of oven




Subject
Side view of equipment (in-process conveyor at left)




Subject
Side view of application station




Subject
In-feed conveyor (1st step of process)




Interior View
None
Existing production line (not new equipment)




Building View
No Signage Present
View of main entrance of business



Building View
Outside view of business



Other
Parking lot looking at downtown Nashville, TN



Building View



Building View
Outside view of parking lot



Address Verification