



National Inspection Services

: 172198 on 08/22/2019

VIN: 17E00E00001098

2001 HITACHI EX-1200 BE-5 BACKHOE

EX-1200 BE-5 BACKHOE Specifications

Engine	Cummins
Operating Hours	32861
Fuel	Diesel
Tire Size F	Tracks
Tire Size R	Tracks

Drive Options

--

Inspection Photos



Notes / Description

--




National Inspection Services

: 172198 on 08/22/2019

VIN: 17E00E00001098

2001 HITACHI EX-1200 BE-5 BACKHOE PHOTOS





National Inspection Services

: 172198 on 08/22/2019

VIN: 17E00E00001098

2001 HITACHI EX-1200 BE-5 BACKHOE

Brakes	
<input type="text"/>	<input type="text"/>
Additional Brake Detail	
NA	

Tires			
Front Tracks	/ 32	/ 32	Rear Tracks
Additional Tire Detail			

General Observations							
Oil Milky? No	Oil Leaks? Yes	Water Leaks? No	Oil in Coolant? No	Clutch Play? NA	Starts? Yes	Drives? Yes	
Safety / Operational Observations							
Lights Work? Yes - All	Wipers Work? NA	Gauges Work? Yes - All	City Horn Works? Yes	Air Horn Works? NA			
Additional Observation Detail							
Oil level very low.							

Wear and Tear Items	
Cab	Floor worn
Interior	Dirty / soiled
Steps	Caked with mud
Body	Dents on rear and side
Paint	Various chips and scratches

Condition report only. National Inspection Services does not guarantee mechanical reliability.

© 2019 National Inspection Services (NIS)
101 W. Shrader St. Liberty, MO 64068
www.nationalinspect.com